



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
November 5, 2005

Supervisor

Mine Name: Anval 1&2

Operator Name: Steven Gale

PO Box 855

Beaver, Utah 84713

Inspector(s): Tom Munson, Daron Haddock

Other Participants: None

Mine Status: Active

Permit number: S/001/038

Inspection Date: 10/26/2005

Time: 8:00 AM - 8:30AM

Weather: Sunny

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

To determine the amount of disturbance associated with the site.

Directions to Site:

See GPS map for location

Inspection Summary:

There exists one small pit onsite that is less than a half of an acre. There was a track hoe at the site.

Conclusions and Recommendations:

The site looked fine and any past reclamation that exists can be released. It would be a good idea for the operator to document anything he wants release on and this can be tracked formally by the Division.

Inspector's Signature

Date: November 5, 2005

TM:jb

cc: Operator


Attachment: GPS & Photos

O:\M001-Beaver\S0010038-Anval\inspections\insp-10262005.doc

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801
telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov

Utah!
Where ideas connect™


0002



ANVIAL 1+2


5010038

← PREVIOUS
RECLAMATION





CURRENT DISTURBANCE



ANVAL 1+2
5010038

Mine Number: S0010038
Mine Name: Anval 1 and 2
Township 29 S Range 09 W Section 29 SLBM

Inspection Date Oct. 26, 2005
 Map Produced by DKS

Acres Disturbed	0.37
Acres Regraded	0
Acres Seeded	0
Road Acres Disturbed	0

Total Acres Disturbed	0.37
------------------------------	-------------

Acres Released	0
Acres Excluded	0
Acres PreExisting	0
Acres Prelaw	0

Legend
 All items symbolized in legend may not be appear on map.



DOQ Imagery date 2/04



0 625
 Feet
 1:2,500 1 inch equals 625 feet
 Verify Scale

Dept. of Natural Resources
 Division of Oil, Gas, and Mining
 Mineral Mines Program

Different data sources and input scales
 may cause misalignment of data layers.
 This product may not meet DGGM
 standards for accuracy and content.